
Assembly Drawing-1




Drill hole diameter: Ø12 mm
Hole depth: 100 mm

NOTE:

- Mark the hole positions on the wall by referencing the bracket mounting holes, then drill holes.
- Use a rubber mallet to tap 6 expansion bolts into the pre-drilled holes until the bolts are fully seated.
- Fasten the support brackets and hanging plate onto the wall in sequence.

Assembly Drawing-2



⚠ SAFETY WARNING

- When installing the unit, ensure the top hanging slot is securely hooked and the bottom locating catch is fully seated into the positioning hole.
- Tightening screws without full engagement will result in false mounting. Risk of unit falling, which may cause personal injury and equipment damage.